

Michael A. Berardi Director Service Engineering Operations Ford Customer Service Division Ford Motor Company P. O. Box 1904 Dearborn, Michigan 48121

January 21, 2015

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: DELIVERY HOLD - Emission Recall 14E03

Certain 2011-2014 Model Year F-Super Duty Vehicles with 6.7L Powerstroke Diesel

Engine

Reprogram Powertrain Control Module

AFFECTED VEHICLES

Vehicle	Model Year	Assembly Plant	Build Dates
F-Super Duty	2011-2014	Kentucky	Job #1 through November 6, 2013

Affected vehicles are identified in OASIS. In addition, for a list of vehicles assigned to your dealership, visit https://web.fsavinlists.dealerconnection.com. This information will be available on January 21, 2015.

REASON FOR THIS EMISSION RECALL

In all of the affected vehicles, the Selective Catalyst Reduction (SCR) system calibration must be updated to meet emission guidelines. In addition, the updated calibration contains additional improvements to the SCR system including reduced temperature sensor faults and improved drivability.

SERVICE ACTION

Before delivering any of the vehicles involved in this recall, dealers are to reprogram the Powertrain Control Module (PCM) using IDS version 93.05 or later. This service must be performed on all affected vehicles at no charge to the vehicle owner.

PLEASE NOTE:

The delivery of uncorrected new vehicles to customers could lead to penalties under applicable state and Federal regulations. Correct all vehicles in your new vehicle inventory prior to delivery.

NOTE: The State of California and the Commonwealth of Massachusetts require the completion of emission recall repairs prior to vehicle registration renewal. For vehicles registered in these states, please provide the owner with a Vehicle Emission Recall Proof of Correction certificate after the repair has been performed. These certificates may be obtained by contacting your regional office.

OWNER NOTIFICATION MAILING SCHEDULE

Owner Letters are expected to be mailed the week of January 26, 2015. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

<u>ATTACHMENTS</u>

Attachment I: Administrative Information

Attachment II: Labor Allowances and Parts Ordering Information

Attachment III: Technical Information

Owner Notification Letter

QUESTIONS & ASSISTANCE

Special Service Support Center (Dealer Assistance Only) _____1-800-325-5621

Sincerely,

Michael A. Berardi

DELIVERY HOLD - Emission Recall 14E03

Certain 2011-2014 Model Year F-Super Duty Vehicles with 6.7L Powerstroke Diesel Engine Reprogram Powertrain Control Module

OASIS ACTIVATED?

Yes, OASIS will be activated on January 21, 2015.

FSA VIN LIST ACTIVATED?

Yes, FSA VIN list will be available through https://web.fsavinlists.dealerconnection.com on January 21, 2015. Owner names and addresses will be available by February 6, 2015.

NOTE: Your FSA VIN list may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

STOCK VEHICLES

- Correct all affected units in your new vehicle inventory before delivery.
- Use OASIS to identify any affected vehicles in your used vehicle inventory.

SOLD VEHICLES

- Owners of affected vehicles will be directed to dealers for repairs.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.

TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this recall.

ADDITIONAL LABOR TIME AND/OR PARTS

Contact the Special Service Support Center (SSSC) if you have any of the following:

- Damage that you believe was caused by the covered condition.
- A condition that requires additional labor and/or parts to complete the repair.
- Aftermarket equipment or non-Ford modifications to the vehicle which might prevent the repair of the covered condition.

Contact the SSSC **prior** to the repair. Please be prepared to provide your requested additional warranty part cost, estimated additional labor time, and dealer specific labor rate. Requests for approval after completion of the repair may not be granted. Ford Motor Company reserves the right to deny coverage for damage in cases where the vehicle owner has not had this recall performed on a timely basis. Additional damaged parts are subject to random selection for return to the Ford Warranty Parts Analysis Center (WPAC).

DELIVERY HOLD - Emission Recall 14E03

Certain 2011-2014 Model Year F-Super Duty Vehicles with 6.7L Powerstroke Diesel Engine Reprogram Powertrain Control Module

OWNER REFUNDS

Refunds are not authorized for this program.

RENTAL VEHICLES

The use of rental vehicles is not approved for this program.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using Direct Warranty Entry (DWE).
- Refer to ACESII manual for claims preparation and submission information.
- Additional labor and/or parts must be claimed on a separate repair line from which the FSA is claimed. Additional labor and /or parts require prior approval from the Special Service Support Center.

DELIVERY HOLD - Emission Recall 14E03

Certain 2011-2014 Model Year F-Super Duty Vehicles with 6.7L Powerstroke Diesel Engine Reprogram Powertrain Control Module

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Reprogram PCM	14E03B	0.7 Hours

PARTS REQUIREMENTS / ORDERING INFORMATION

Parts are not required to complete this repair.